HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH 307 CORNELIUS HARNETT BOULEVARD LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

Name: Kevin Tyndall Phone #: 910-237-4237

Address: 1014 West Core Road Dunn, NC 28334

Name of Mobile Home Park or S/D: NA

Name of Owner (if different): Casper Johnson

Address of Owner (if different): 3964 Hwy 301 South

Property Location (State Road name and #): 3964 Hwy 301 South

Purpose of Inspection: Addition - Covered Front Porch (10'x20') - Original Porch (6'x9')

The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If the system should malfunction, the owner is responsible for any necessary repairs.

THIS INSPECTION IS VOID IF:

- 1. the intended use of the septic system should change, and/or
- 2. the system should fail or malfunction, and/or
- 3. the owner or tenant of the property change, and/or
- 4. after six months

BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM DO NOT DRIVE OR PARK ON SEPTIC SYSTEM

AUTHORIZATION OF EXISTING SYSTEM

TEK

06/07 Date

Signature of Environmental Health Specialist