| Pursuant to NCGS 153A-352 (C1, 2, 3 D), |
|---|
| I WAXNER. DASHIELD, PE have |
| personally (or had an agent under my direct supervision) performed an |
| inspection of the work done at the following location address: |
| 375 TYLERSTONE DR FUGUAY-VARINA, NC |
| Scope of work was: STRUCTURAL INSPECTION OF EXISTING SON ROOM |
| • |
| I hereby certify that the work done meets all aspects of the North |
| Carolina Building and technical codes in effect at the time of my |
| inspection. |
| Signature Way Plad Date 07-08-17 |
| |

Seal Here

2 veltico a mi

MA JOSEPH A TELEPHONE

Mar 10 MC08 1234-325 (CT. 213 D)

SERVICE STATE OF SERVICE SERVICES

Middleso Acros

DANGE OF THE STATE OF THE STATE

er artify that the work done meets all aspects of the Notice of the Notice of the Section of the

The series