Department of Environment, Health and Natu Division of Environmental Health On-Site Wastewater Section

Applicant:

Owner:

Description

System Type(s)

Site LTAR

Available Space (.1945)

Initial

System

Repair System

the

.88

sources

Sheet: Property ID: Lot #: File #:

Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Water Evalua Type o	ss: sed Facility:	1.45 1: 1 Auge	Date Desig Prope Public In Boring Sewage	Evaluated: In Flow (.1949):246 Introduction of the content of the	II ☐ Spring		er		
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	LTIZ	0-36	5L ,						
_		37.48	EC /	n 6ansor P.					153
								,	

Other Factors (.1946): Site Classification (.1948): Evaluated By: Others Present: COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	1	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

**STRUCTURE** SG-SINGLE GRAIN M- MASSIVE **CR-CRUMB** GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY PR-PRISMATIC

**MINERALOGY** SLIGHTLY EXPANSIVE

**EXPANSIVE** 

Show profile locations and other site features (dimensions, references or benchmark, and North)