PREPARED 7/03/18, 14:11:27 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

3.00

DATE 7/05/18

ADDRESS . : 30 TANAWHA CT

SUBDIV: ACC ANDERSON CRK CROSSING 78LT

CONTRACTOR : HOBBS BUILDER, INC.,

PHONE: (910) 624-1242

OWNER . . : HARKA YOSHINORI & YOON NHAM PHONE : (910) 497-8176

PARCEL . .: 01-0535-24- -0100- -65-

APPL NUMBER: 17-50042775 CP ADD & ALTER RESIDENTIAL

DIRECTIONS : T/S: 11/16/2017 01:16 PM LLUCAS ----

30 TANAWHA CT - ANDERSON CREEK CROSSING LOT#140 - TURN LEFT ONTO RAY RD - TURN LEFT ONTO FALLS CREEK DR - TURN RIGHT

ONTO TANAWHA CT

STRUCTURE: 000 000 RENO & ADDIT FOR HANDICAPP ACCESS

FLOOD ZONE . . . : FLOOD ZONE X

BATHS 2 # BEDROOMS :

SEPTIC - EXISTING? . . . : SEWER WATER SUPPLY

PERMIT: CPBP 00 CP BUILDING PERMIT REQUESTED INSP DESCRIPTION			
TYP/SQ	COMPLETED		RESULTS/COMMENTS
B101 01	12/08/17	TSG	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 003063641
	12/08/17	AP	T/S: 12/07/2017 09:49 AM LLUCAS
			PERMIT & PLANS ON BACK PORCH
B103 01	1/12/18	JH	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 003075231
	1/12/18	AP	T/S: 01/11/2018 09:15 AM LLUCAS
B105 01	2/08/18	JH	R*OPEN FLOOR VRU #: 003086555
	2/08/18	AP	
R425 01	3/15/18	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003101839
	3/15/18	DA	T/S: 03/14/2018 12:06 PM LLUCASNO ONE HOME
R425 02	3/19/18	JH	FOUR TRADE ROUGH IN VRU #: 003102831
	3/19/18	DA	1) Missing insulation baffles.2) Need 8- 16 penny nails each end of structual nail guard over sink.3) Need to double all studs for drain line at sink per code.4) Midstory strapping on 2" pipe.5) Need 2 jack studs each end of door header for bathroom.
R425 04	3/23/18	JH	FOUR TRADE ROUGH IN VRU #: 003105115
	3/23/18	AP	νιο _π . σσστοστί
R425 03	3/26/18	ЈН	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003105236
	3/26/18	CA	T/S: 03/22/2018 11:51 AM LLUCAS
			PLEASE CALL JIMMY HOBBS IF ANY PROBLEMS - 910-624-1242
			4 trade roughin passed 3-23-18
1129 01	3/29/18	JH	R*INSULATION INSPECTION VRU #: 003107738
	3/29/18	AP	
2429 01	6/28/18	JH	FOUR TRADE FINAL VRU #: 003145304
	6/28/18	DA	1) Caulk toilet.2) Need engineer letter for walls removed in
			kitchen & installed beam.3)Need 3 1/2" handrail at steps & ramps.
429 02	7/03/18	JH	FOUR TRADE FINAL VRU #: 003147240
	7/03/18	CA	PER JIMMY HOBBS
2425 05	7-5-18	STY	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003147824 T/S: 07/03/2018 01:41 PM LLUCAS

FOR OLD BATHROOM

M. A. COLVIN ENGINEERING & CONSULTING, INC.

Harnett County Planning & Inspections Department 108 E. Front Street Lillington NC 27546 Attn. Mr. Jimmy Hall, Senior Building Inspector

July 2nd, 2018

Re:

Anderson Crossing Subdivision

30 Tanawha Court Spring Lake NC 28390

Permit Application No. 1750042775

Subject:

Engineer's Certification Letter for Structural Adequacy

On Friday June 29th 2018, I evaluated the existing cased opening and column support at the above referenced address. Drilled core test were performed to verify the existing header and supporting timber columns. A crawlspace investigation was also included to confirm adequate load path from the support columns to the foundation and footing. In accordance with the 2012 edition of the North Carolina Residential Code Section R301.1.3 Engineered Design, it is my professional opinion that the structural support system for the existing cased opening is structurally adequate. I hereby certify this document by my seal in accordance with NCAC 56.1103.

Myers A. Colvin Sr. PE

S NGINE CONTINUES OF THE PROPERTY OF THE PROPE

07-02.2018