

ADDRESS : 29 SANDHILL CRANE CT SUBDIV: CAROLINA LAKES
CONTRACTOR : WICKER CONSTRUCTION CORP. PHONE : (919) 258-9646
OWNER : MARTIN JESSE L PHONE : (910) 364-1580
PARCEL : 03-9585-04- -0021- - -
APPL NUMBER: 18-50043214 CP ADD & ALTER RESIDENTIAL
DIRECTIONS : T/S: 02/01/2018 11:09 AM BPETRICH --
29 SANDHILLS CRANE CT SANFORD 27330
CAROLINA LAKES #21

STRUCTURE: 000 000 FINISH UPSTAIRS - ADDING 2BD 1BA

FLOOD ZONE : FLOOD ZONE X
BATHS : 4 # BEDROOMS : 5.00
SEPTIC - EXISTING? : SEWER WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R425 01	2/08/18 2/08/18	TSG DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003086808 T/S: 02/07/2018 01:34 PM BPETRICH ----- 1-install air barriers where required 2-fire caulk top plates 3-increase fire rating on garage ceiling 4- several nail plates missing.
R425 02	2/16/18 2/16/18	TSG AE	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003090388 T/S: 02/15/2018 02:57 PM DJOHNSON ----- Contractor to call for inspection of adding drywall to garage ceiling at final
R425 03	4/24/18 4/24/18	TSG AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003118080 T/S: 04/23/2018 01:44 PM JBROCK ----- T/S: 04/24/2018 03:06 PM SGUY -----
R429 01	4/24/18 4/24/18	TSG DA	FOUR TRADE FINAL TIME: 17:00 VRU #: 003118072 T/S: 04/23/2018 01:44 PM JBROCK ----- 1-DUCT PRESURE TEST REQUIRED ON TOTAL NEW SYSTEM. 2-INSULATE DOOR TO A/C UNIT 3-AIR ADMITANCE VALVE MISSING 4-VERIFY CO DETECTORS. 5- VERIFY SMOKE DETECTORS ARE INTERCONNECTED.
R429 02	4/26/18 4/26/18	TSG DA	FOUR TRADE FINAL TIME: 17:00 VRU #: 003118858 T/S: 04/25/2018 12:49 PM DJOHNSON ----- STILL MISSING DUCT PRESURE TEST
R429 03	6/04/18	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 003134749 T/S: 06/01/2018 11:30 AM LLUCAS -----

COMMENTS AND NOTES