

ADDRESS : 1310 OLIVE BRANCH RD
CONTRACTOR : FAULKNER, THOMAS JOSEPH, JR.
OWNER : KEHLER MARK A & ELSIE L
PARCEL : 08-0642- - -0009- - -
APPL NUMBER: 18-50044099 CP ADD & ALTER RESIDENTIAL
DIRECTIONS : T/S: 05/23/2018 03:14 PM LLUCAS ----
1310 OLIVE BRANCH RD
NORTH ON 401 TO LEFT ON OLIVE BRANCH RD
****THIS CUSTOMER ORIGINALLY WENT
STRAIGHT TO ENVIRONEMNTAL HEALTH AND
GOT A SEPTIC PERMIT, I HAVE TALKED TO
SUSAN AND LET HER KNOW THAT WE NEED TO
HAVE THE IMPROVEMENT PERMIT SCANNED IN
TO LASERFISHCE FOR THIS APPLICATION****

SUBDIV:
PHONE : (919) 946-1196
PHONE :

✓ good @ Environmental,
spoke with Susan 6/26
BP

STRUCTURE: 000 000 INTERIOR RENOVATIONS DONE W/O PERMITS

FLOOD ZONE : FLOOD ZONE X

BATHS : 2

BEDROOMS : 4.00

SEPTIC - EXISTING? : 2

WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R429 01	6/01/18 6/01/18	MC DA	FOUR TRADE FINAL TIME: 17:00 VRU #: 003134327 T/S: 05/31/2018 12:47 PM DJOHNSON WOULD LIKE AFTER LUNCH IF YOU COULD PLEASE CAUSE MR FAULKNER ABOUT 30 MINS BEFORE GOING THERE.919-946-1196 T/S: 06/01/2018 03:15 PM MCOOK 1 vent at hall bath not terminated properly 2. need duct blast test 3. install anti-tip devise on stove 4. shingles not properly lapped at gable.
R429 02	6/27/18 1/1 6/27/18	TI DP AP	FOUR TRADE FINAL TIME: 17:00 VRU #: 003144540 T/S: 06/25/2018 04:15 PM LLUCAS

COMMENTS AND NOTES

① ~~need duct blast test~~
② ~~can not occupy home without CO.~~