

# SITE/SOIL EVALUATION FOR ON-SITE W STEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-18	0-18	0-4	0-18	0-10									
TEXTURE GROUP	.1941(A)(1)	SC1	SC1	OS	SC1	SL									
CONSISTENCE	.1941	F	F		F	VFr									
STRUCTURE	.1941(A)(2)	AK	SK		SK	F									
MINERALOGY	.1941(A)(3)	SK	SK		SK	Nc4									
HORIZON 2 DEPTH		19+	18+	4-72		10-27									
TEXTURE GROUP	.1941(A)(1)	Sm	Sm	SL		SC1									
CONSISTENCE	.1941			VFr		F									
STRUCTURE	.1941(A)(2)			O		SK									
MINERALOGY	.1941(A)(3)			Nc4		SK									
HORIZON 3 DEPTH				12-32		27+									
TEXTURE GROUP	.1941(A)(1)			SC1		Sm									
CONSISTENCE	.1941			F											
STRUCTURE	.1941(A)(2)			SK											
MINERALOGY	.1941(A)(3)			SK											
HORIZON 4 DEPTH				5-60											
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948	OS/PS	OS/PS	OS	OS/PS	OS/PS									
LONG TERM ACCEPTANCE RANGE	.1955	.4	.4	.4	.4	.4									

6400 B2



