

COMMENTS:

6" OF STONE

21 $\frac{1}{2}$   
20 $\frac{1}{4}$

• SITE VISIT ON 6/9/08 - MET W/ MIKE HENNING.

• TANKS INSTALLED FOR DWG PUMP + HAVE PERMIT. INFORMED MIKE

THAT INSPECTION OF TANKS MUST BE DONE PER LINE 18 OF PERMIT.

• INSPECTED THE TANKS AND WILL RETURN ON 6/10 TO FINISH LEAK TEST

• TANKS INSPECTED IN CASE HOW PERMIT IS INSTALLED IN THE FUTURE

• WATER MEASURED TO TOP OF LID REST ON INLET END - ST 21 $\frac{1}{2}$ " PT 20 $\frac{1}{4}$ "

• RETURN VISIT ON 6/10/08

• MEASUREMENTS TAKEN AGAIN - ST 21 $\frac{1}{2}$ " PT 20 $\frac{1}{4}$ "