

County of Harnett  
Building Inspections Department  
Planning Services

**Certificate of Compliance: \_\_\_ Occupancy: X**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Detached Garage

**Permit Numbers**

Name: Harley G and Ruth Frame

Building: 12-50029398

Electrical: 12-50029398

Address: 1296 Young Road

Insulation: 12-50029398

Angier NC 27501

Plumbing: 12-50029398

Mechanical: 12-50029398

MFG Home: NANANANANA

Date: 10-30-2013

Building Official: BSutton

ADDRESS \* : 1296 YOUNG RD SUBDIV: THE H P YOUNG LANDS  
 CONTRACTOR : PHONE :  
 OWNER : FRAME HARLEY G & RUTH J PHONE :  
 PARCEL : 07-0692- - -0085- - -  
 APPL NUMBER: 12-50029398 CP GARAGE/CARPORT RESIDENTIAL DETACHED  
 DIRECTIONS : T/S: 07/17/2012 11:10 AM VBROWN ----  
 1296 YOUNG RD ANGIER 27501.  
 T/S: 08/17/2012 11:47 AM JBROCK ----  
 REF #0850019942 - POOL  
 POOL NEEDS TO BE CO'ED AT THE SAME TIME  
 AS THE GARAGE

STRUCTURE: 000 000 28X54 DET GARAGE STORAGE  
 FLOOD ZONE : FLOOD ZONE X  
 PROPOSED USE : DET GAR SEPTIC - EXISTING? : EXISTING  
 WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B111 01	8/22/12 8/23/12	DT AP	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002268894 T/S: 08/21/2012 11:34 AM VBROWN ---- CUSTOMER REQUEST PM INSP INCASE OF RAIN HE CAN CLEAN IT OUT FOR YOU.
R125 01	9/11/12 9/11/12	BS AE	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002276905 SHEATHING INSPECTION - CUSTOEMR PAID T/S: 09/10/2012 01:07 PM JBROCK ---- T/S: September 11, 2012 11:50 AM BSUTTON ---- OSB must maintain 6 inches clearance to grade. At front apron, remove OSB, and replace with 1/2 inch treated plywood. We can verify this correction at rough ins. OK to install siding
H824 01	10/10/12 10/10/12	JM AP	ENVR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002290203 T/S: 10/11/2012 10:52 AM SSTEWARD ---- T/S: 10/11/2012 10:53 AM SSTEWARD ----
R425 01	2/07/13 2/07/13	BS CA	FOUR TRADE ROUGH IN VRU #: 002336136 T/S: February 07, 2013 01:15 PM BSUTTON ---- per hoomeowner
R425 02	4/04/13 4/04/13	KS AP	FOUR TRADE ROUGH IN VRU #: 002360741 T/S: 04/04/2013 11:49 AM KSLATTUM ----
I129 01	4/18/13 4/18/13	BS AP	R*INSULATION INSPECTION VRU #: 002368690 T/S: April 18, 2013 01:48 PM BSUTTON ----
R429 01	10/22/13 10/23/13	BS DA	FOUR TRADE FINAL TIME: 17:00 VRU #: 002455251 T/S: 10/21/2013 09:16 AM DJOHNSON ---- T/S: October 23, 2013 10:31 AM BSUTTON ---- rec covered or missing at bedroom. Handrail at bottom of stairs needs return to wall or remove.
R429 02	10/30/13 <i>10-30-13</i>	TI <i>APBS</i>	FOUR TRADE FINAL TIME: 17:00 VRU #: 002458842 T/S: 10/29/2013 08:37 AM DJOHNSON ----

COMMENTS AND NOTES