
ADDRESS . : 266 BRADLEY RD SUBDIV:
CONTRACTOR : PHONE :
OWNER . . : DE HOOG GARLAND & RUTH PHONE :
PARCEL . . : 08-0642- - -0015- - -
APPL NUMBER: 17-50041567 CP GARAGE/CARPORT RESIDENTIAL DETACHED
DIRECTIONS : T/S: 06/06/2017 02:05 PM LBENNETT --
HWY 401 TO LEFT ON CHRISTIAN LIGHT RD -
TO LEFT ON BRADLEY - SECOND HOUSE ON
THE RIGHT

STRUCTURE: 000 000 40X40 DETACHED GARAGE

FLOOD ZONE : FLOOD ZONE X
PROPOSED USE : GARAGE SEPTIC - EXISTING? : EXIST
WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/18/17	JLP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002998929
	7/18/17	AP	T/S: 07/18/2017 03:39 PM JPERRY -----
B103 01	7/28/17	JLP	R*BLDG FOUND & TEMP SVC POLE VRU #: 003004634
	7/28/17	AP	T/S: 07/28/2017 01:43 PM JPERRY -----
B111 01	8/07/17	TI	R*BLDG SLAB INSP/TEMP SVC POLE VRU #: 003008514
	<u>8-7-17</u>	<u>APB</u>	

----- COMMENTS AND NOTES -----

Enoch Engineers, P.A.

Materials & Tests Division
1403 NC Highway 50 South
Benson, NC 27504
919-894-7765

Report

Client: CONCRETE FOUNDATIONS Technician: BH
Project: _____ Date: 8.4.17
Location: 266 BRADLEY RD Contractor: C/O CHAD RIDGLEY
Lot #: FUQUAY VAZINA


Services Performed:

- Nuclear Density Test
- Concrete Tests
- Asphalt Tests
- Site Inspection
- Foundation Inspection
- Structural Inspection
- Proof-roll

- Steel Inspection
- Sub-Grade Inspection
- H.U.D. Inspection
- LUGG Footing Inspection
- Footing Inspection
- Other: _____

Remarks: PERFORMED NOT ON PAD AT SITE NOTED
ABOVE USING TARGET DENSITY OF 115 PCF. SOILS
CONFIRMED A COMPACTION \geq 95%.

NTS.



Comp = 97.7 %
DD = 112.4 PCF
WD = 122.5 PCF
MC = 8.9 %
@ 8" DEPTH

Technician: _____

B. HEATH