


APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		0-24	0-22	0-12	0-22					
Texture Group	.1941(A)(1)	sl	sl	sl	sl					
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 2 DEPTH		24-30	22-36	12-24	22-28					
Texture Group	.1941(A)(1)	sl	sl	sl	sl					
Consistence	.1941			EP						
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 3 DEPTH		30-34			28-38					
Texture Group	.1941(A)(1)	sl			sl					
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942	32"		22"						
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/1956									
CLASSIFICATION	.1948	PS	PS	PS	PS					
LONG TERM ACCEPTANCE RATE	.1955	.5	.5	X	.6					



3 x 70' Lanes  
 18" deep  
 on asphalt