

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		0-16	0-14	0-18	0-16	0-28	0-14	0-12	0-14	
Texture Group	.1941(A)(1)	4/CL	4/SL	4/SL	4/SL	4/PL	4/SL	4/SL	4/SL	
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 2 DEPTH		16-36	14-36	18-26	16-36	28-38	14-36	12-36	14-36	
Texture Group	.1941(A)(1)	SL	SL	SL	SL	SL	SL	SL	SL	
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 3 DEPTH				18-38						
Texture Group	.1941(A)(1)			SL/SL						
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942	—	34"	—	34"	—	34"	34"	34"	
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/1956									
CLASSIFICATION	.1948	PS	PS	PS	PS	PS	PS	PS	PS	
LONG TERM ACCEPTANCE RATE	.1955	.5/45	.45	.5	.45	.5	.45	.45	.45	

3x100 lines
at 18-20" deep
4' fall from
house to
field.

