RTMENT TION

№13973

old

OPERATIONS PERMIT

| Name: (owner) | mes brillard Pine Grove Deu SR# 141 | New Installation Septic Tank |
|------------------------------|---|-------------------------------------|
| Property Location: | SR# | Repairs Nitrification Line |
| | Subdivision Heather Brook Est | |
| <u> </u> | TAX ID# | Quadrant # |
| Contractor: \\ellar | Blown | Registration # |
| Basement with Plum | | |
| Water Supply: | Well Public Community | |
| Distance From Well: | ft. | |
| Following are the sp | pecifications for the sewage disposal sys | tem on above captioned property. |
| T | Jan 1 7 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 | |
| Type of system: | | |
| Size of tank: | Septic Tank: gallons Pu | mp Tank: gallons |
| Subsurface | No. of ditches exact length of each ditch 50 ft | width of depth of |
| Drainage Field French Drain: | Linear feet | ditches ft. ditches in. |
| | , | 0.30,2000 |
| PERMIT NO | • | / 1.10 |
| 1 | mspected | by: Environmental Health Specialist |
| | | |
| 35 | | |
| | 1111 | - |
| | | * |
| | | 1 |
| Α | | |
| 011 | 35' | 14 h |
| Pl 1 | ∠35' | |
| Pl | 235 | |
| Pl 25 | 235 | |
| Pl 2 | 235' | |