

OPERATIONS PERMIT

Name: (owner) Arden & Marlene Purvis New Installation Septic Tank
 Property Location: SR# 1153 Repairs Nitrification Line
 Subdivision Cameron Hill Acres Lot # 45
 TAX ID# _____ Quadrant # _____
 Contractor: Mike Ray Registration # _____

Basement with Plumbing: Garage:
 Water Supply: Well Public Community
 Distance From Well: 50 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other _____
 Size of tank: Septic Tank: 1000 gallons Pump Tank: _____ gallons
 Subsurface Drainage Field No. of ditches 1 exact length of each ditch 200 ft. width of ditches 3 ft. depth of ditches 18 3/4 in.
 French Drain: _____ Linear feet

PERMIT NO. 16788 Date: 01-18-01
 Inspected by: Joe Watts
 Environmental Health Specialist

