

02 Jan 2001 (UPD)


Brande - Lot #

① 0-22 W/S
22-37 SCL
(13) PS

④ 0-20 W/S
20-36 SCL
(13)

② 0-20 W/S
20-36 SCL
(13) PS

③ 0-26 W/S
26-38 SCL
(13) PS



Evaluated for
new permit on
02 Jan 2001
(UPD)

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		0-6	0-6	0-26	0-18	0-16	0-19	0-22		
Texture Group	.1941(A)(1)	u/slc	u/slc	u/slc	u/slc	u/slc	u/slc	u/slc		
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 2 DEPTH		6-34	6-30	26-32	18-34	16-36	19-36	22-38		
Texture Group	.1941(A)(1)	slc	slc	slc	slc	slc	slc	slc		
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 3 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942	34"	24"	—	34"	33"	34"	34"		
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/1956									
CLASSIFICATION	.1948	R ₁	R ₂	R ₃	R ₅	R ₁	R ₀	R ₃		
LONG TERM ACCEPTANCE RATE	.1955	.4	.3	.4	.3	.3	.3	.3		

