

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		G-26	G-30	G-30	O-30					
Texture Group	.1941(A)(1)	LS	LS	LS	LS					
Consistence	.1941	VEr	VEr	VEr	VEr					
Structure	.1941(A)(2)	G	G	G	G					
Mineralogy	.1941(A)(3)	NEu	NEu	NEu	NEu					
HORIZON 2 DEPTH		U6-32	30-36	30-36	30-36					
Texture Group	.1941(A)(1)	SCL	SCL	SCL	SCL					
Consistence	.1941	Fr	Fr	Fr	Fr					
Structure	.1941(A)(2)	SBR	SBR	SBR	SBR					
Mineralogy	.1941(A)(3)	SEu	SEu	SEu	SEu					
HORIZON 3 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942	32"								
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/.1956									
CLASSIFICATION	.1948	US/P5	P5	P5	P5					
LONG TERM ACCEPTANCE RATE	.1955	0.45	.5	0.5	0.5					

45 <sup>6</sup>/<sub>200</sub>

