


FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		0-40	0-74	0-42	0-22	0-26				
Texture Group	.1941(A)(1)	C/SCL	C/S	C/SCL	C/SCL	C/SCL				
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 2 DEPTH			14-36		22-36	26-32				
Texture Group	.1941(A)(1)		SCL		SCL	SCL				
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 3 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942	—	—	—	—	—				
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/1956									
CLASSIFICATION	.1948	S	PS	PS	PS	PS				
LONG TERM ACCEPTANCE RATE	.1955	.8	.5	.8	.5	.5				



150' from road clear

3 x 80' lines
18-24" deep