

# OPERATIONS PERMIT

Name: (owner) Pine Grove Dev  New Installation  Septic Tank  
 Property Location: SR# 1141  Repairs  Nitrification Line  
 Subdivision Heather Brook Lot # 38  
 TAX ID# \_\_\_\_\_ Quadrant # \_\_\_\_\_  
 Contractor: T BROWN Registration # \_\_\_\_\_

Basement with Plumbing:  Garage:   
 Water Supply:  Well  Public  Community  
 Distance From Well: 50 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system:  Conventional  Other \_\_\_\_\_  
 Size of tank: Septic Tank: 1000 gallons Pump Tank: \_\_\_\_\_ gallons  
 Subsurface Drainage Field No. of ditches 1 exact length 400 ft. width of 3 ft. depth of 18 in.  
 French Drain: \_\_\_\_\_ Linear feet

Date: 2-27-01

PERMIT NO. \_\_\_\_\_

Inspected by: JULIUS  
 Environmental Health Specialist

