



APPLICANT NAME _____

DATE _____

FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		0-20	0-16	0-36	0-38	0-30				
Texture Group	.1941(A)(1)	0-20	s/su	s/su	s/su	s/su				
Consistence	.1941	s/su								
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 2 DEPTH		20-36	16-36							
Texture Group	.1941(A)(1)	s/su	s/su							
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 3 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942	—	—	—	—	—				
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/1956									
CLASSIFICATION	.1948	ps	ps	ps	ps	ps				
LONG TERM ACCEPTANCE RATE	.1955	.6	.6	.6	.6	.6				



 2 X 100' lines
 on contours
 behind home



PLAN APPROVAL
 DISTRICT NA USE SWMH
 #BEDROOMS 2
1-18-01 Williams
 Date Zoning Administrator

Required Property Line Setbacks

	Minimum	Actual
Front	<u>35</u>	<u>200</u>
Side	<u>10</u>	<u>50</u>
Corner	<u>20</u>	<u>100</u>
Rear	<u>25</u>	<u>300</u>
Nearest Building	<u>10</u>	<u>100</u>

S 83°48'02"E
 18.20'