


# SITE/S... EVALUATION FOR ON-SIT... WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
<b>LANDSCAPE POSITION</b>	.1940										
<b>SLOPE (%)</b>	.1940										
<b>HORIZON 1 DEPTH</b>		6-76									
Texture Group	.1941(A)(1)	25									
Consistence	.1941	VF									
Structure	.1941(A)(2)	G									
Mineralogy	.1941(A)(3)	UV									
<b>HORIZON 2 DEPTH</b>											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
<b>HORIZON 3 DEPTH</b>											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
<b>HORIZON 4 DEPTH</b>											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
<b>SOIL WETNESS</b>	.1942										
<b>RESTRICTIVE HORIZON</b>	.1944										
<b>SAPROLITE</b>	.1943/.1956										
<b>CLASSIFICATION</b>	.1948	5									
<b>LONG TERM ACCEPTANCE RATE</b>	.1955	-8									



Pa.