

# SITE/S... EVALUATION FOR ON-SIT WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-12	0-18	0-22											
Texture Group	.1941(A)(1)	SL	SL	SL											
Consistence	.1941	Vb	Vb	Vb											
Structure	.1941(A)(2)	G	G	G											
Mineralogy	.1941(A)(3)	Nv	Nv	Nv											
HORIZON 2 DEPTH		12-28	18-72	22-36											
Texture Group	.1941(A)(1)	C	C	SC											
Consistence	.1941	K:	K:	K:											
Structure	.1941(A)(2)	SPK	SPK	SPK											
Mineralogy	.1941(A)(3)	SCV	SCV	SCV											
HORIZON 3 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942	24													
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948	SPS	PS	PC											
LONG TERM ACCEPTANCE RATE	.1955	.3	.3	.4											

