

# SITE/S... EVALUATION FOR ON-SIT WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-30	0-18	0-14	0-12	0-30								
Texture Group	.1941(A)(1)	SL	SL	SL	SL	SL								
Consistence	.1941	Vhr	Vhr	Vhr	Vhr	Vhr								
Structure	.1941(A)(2)	G	G	G	G	G								
Mineralogy	.1941(A)(3)	Nay	Nay	Nay	Nay	Nay								
HORIZON 2 DEPTH		70-80	18-30	14-22	12-30									
Texture Group	.1941(A)(1)	SC1	SC1	SC	SC1									
Consistence	.1941	Fr	Fr	Fr	Fr									
Structure	.1941(A)(2)	SBL	SBL	SBL	SBL									
Mineralogy	.1941(A)(3)	Say	Say	Say	Say									
HORIZON 3 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 4 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
SOIL WETNESS	.1942			200										
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/.1956													
CLASSIFICATION	.1948	S	PS	OS	PS	S								
LONG TERM ACCEPTANCE RATE	.1955	.8	.35		.4	.8								

6"

R-1

