

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

| FACTORS                   |             | PROFILES |       |      |      |      |   |   |   |   |    |  |  |  |  |
|---------------------------|-------------|----------|-------|------|------|------|---|---|---|---|----|--|--|--|--|
|                           |             | 1        | 2     | 3    | 4    | 5    | 6 | 7 | 8 | 9 | 10 |  |  |  |  |
| LANDSCAPE POSITION        | .1940       |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| SLOPE (%)                 | .1940       |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| <b>HORIZON 1 DEPTH</b>    |             |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| Texture Group             | .1941(A)(1) | C-26     | C-28  | C-27 | C-26 | C-30 |   |   |   |   |    |  |  |  |  |
| Consistence               | .1941       | CS       | CS    | CS   | CS   | CS   |   |   |   |   |    |  |  |  |  |
| Structure                 | .1941(A)(2) | √hr      | √hr   | √hr  | √hr  | √hr  |   |   |   |   |    |  |  |  |  |
| Mineralogy                | .1941(A)(3) | G        | G     | G    | G    | G    |   |   |   |   |    |  |  |  |  |
| <b>HORIZON 2 DEPTH</b>    |             |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| Texture Group             | .1941(A)(1) | 26-32    | 26-32 |      |      |      |   |   |   |   |    |  |  |  |  |
| Consistence               | .1941       | SC       | SC    |      |      |      |   |   |   |   |    |  |  |  |  |
| Structure                 | .1941(A)(2) | h        | h     |      |      |      |   |   |   |   |    |  |  |  |  |
| Mineralogy                | .1941(A)(3) | SO6      | SO6   |      |      |      |   |   |   |   |    |  |  |  |  |
| <b>HORIZON 3 DEPTH</b>    |             |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| Texture Group             | .1941(A)(1) |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| Consistence               | .1941       |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| Structure                 | .1941(A)(2) |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| Mineralogy                | .1941(A)(3) |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| <b>HORIZON 4 DEPTH</b>    |             |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| Texture Group             | .1941(A)(1) |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| Consistence               | .1941       |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| Structure                 | .1941(A)(2) |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| Mineralogy                | .1941(A)(3) |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| SOIL WETNESS              | .1942       | 72"      |       |      |      | 70"  |   |   |   |   |    |  |  |  |  |
| RESTRICTIVE HORIZON       | .1944       |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| SAPROLITE                 | .1943/.1956 |          |       |      |      |      |   |   |   |   |    |  |  |  |  |
| CLASSIFICATION            | .1948       | P5       | P5    | P5   | P5   | P5   |   |   |   |   |    |  |  |  |  |
| LONG TERM ACCEPTANCE RATE | .1955       | .4       | .5    | .8   | .8   | .8   |   |   |   |   |    |  |  |  |  |



Ld.