

# SITE/SURVEY EVALUATION FOR ON-SIT WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-18	0-12	0-12		0-38									
Texture Group	.1941(A)(1)	L	LS	LS		SC									
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 2 DEPTH		18-26	12-24	12-24											
Texture Group	.1941(A)(1)	SC	SC	SC											
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 3 DEPTH		26-36	24-36	24-36											
Texture Group	.1941(A)(1)	SC	SC	SC											
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942	26"	26"	26"											
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948														
LONG TERM ACCEPTANCE RATE	.1955	PS LPP	PS LPP				.6	.6	.6	.6	.6				

Pump to  
 the front  
 3x70  
 18"

LPP front

