

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0.30			0.24						
Texture Group	.1941(A)(1)	LS			LS						
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 2 DEPTH		50.48			24.36						
Texture Group	.1941(A)(1)	SCL			SCL						
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 3 DEPTH					36.48						
Texture Group	.1941(A)(1)				SC						
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RATE	.1955	.6	.6	.6	.4	.4	.4	.4			

Handwritten: C.A.K. = 4

Handwritten: 1 x 300
18.24

Handwritten: 900
4(360)



□ Home is 28 x 56 (without tongue)
3 bedroom
2 baths

1 x 300
18.24

Charles TACIA III