


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		3"	13"	12"	12"	12"	12"	14"			
Texture Group	.1941(A)(1)	C	PO					PM			
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)	VS/VP									
HORIZON 2 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 3 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948	U3	U3	U3	U3	U3	U3	U3			
LONG TERM ACCEPTANCE RATE	.1955										



MEET w/ EO THOMAS ON
6/14. VERIFIED BEAR
PROP. LIVE

8-10
CHECKED
ON
6/14
PM @
12" OR LESS