# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

**APPLICANT NAME** _____ **DATE** _____

| FACTORS | | PROFILES | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| **LANDSCAPE POSITION** | .1940 | | | | | | | | | | |
| **SLOPE (%)** | .1940 | | | | | | | | | | |
| **HORIZON 1 DEPTH** | | 0-10 | | | | | | | | | |
| Texture Group | .1941(A)(1) | SL | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| **HORIZON 2 DEPTH** | | 10+ | | | | | | | | | |
| Texture Group | .1941(A)(1) | SL | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| **HORIZON 3 DEPTH** | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| **HORIZON 4 DEPTH** | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| **SOIL WETNESS** | .1942 | | | | | | | | | | |
| **RESTRICTIVE HORIZON** | .1944 | | | | | | | | | | |
| **SAPROLITE** | .1943/.1956 | | | | | | | | | | |
| **CLASSIFICATION** | .1948 | | | | | | | | | | |
| **LONG TERM ACCEPTANCE RATE** | .1955 | | | | | | | | | | |