

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

DATE _____

7/12/01

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L3	LS								
SLOPE (%)	.1940	0-2%	0-2%								
HORIZON 1 DEPTH		0-30	0-30	0-30	0-30						
Texture Group	.1941(A)(1)	SL	SL	SL	SL						
Consistence	.1941	VFR	VFR	VFR	VFR						
Structure	.1941(A)(2)	G	G	G	G						
Mineralogy	.1941(A)(3)	N5/NP	N5/NP	N5/NP	N5/NP						
HORIZON 2 DEPTH		30-40	30-42	30"	30"						
Texture Group	.1941(A)(1)	SCC	SCC	SCC	SCC						
Consistence	.1941	FR/VFR	FR/VFR	FR	FR/VFR						
Structure	.1941(A)(2)	SBK/C	SBK/C	SBK/C	SBK/C						
Mineralogy	.1941(A)(3)	SS/SP	SS/SP	SS/SP	SS/SP						
HORIZON 3 DEPTH		40	42"								
Texture Group	.1941(A)(1)	C	IC								
Consistence	.1941	FR	FR								
Structure	.1941(A)(2)	SBK	SBK								
Mineralogy	.1941(A)(3)	SS/SP	SS/SP								
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948	PS	PS	PS	PS						
LONG TERM											
ACCEPTANCE RATE	.1955	.5	.5	.5	.5						

BARN

3 80 LINES

18"-24"

CON
REPAIR

30"

87'

27x64

WHITE LINE
OFF RD

138'