

SITE/S EVALUATION FOR ON-SI WASTEWATER


APPLICANT NAME _____

DATE _____

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		17-42												
Texture Group	.1941(A)(1)	SC												
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 2 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 3 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 4 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/.1956													
CLASSIFICATION	.1948													
LONG TERM ACCEPTANCE RATE	.1955													

3270
18.24

To
Bill
John
↓



Some
LPP

Some LPP
90

Telephone P-1

SITE PLAN APPROVAL

DISTRICT RAZOR USE DRMHT

#BEDROOMS 3

Date 24 Aug 11 CBell
Zoning Administrator

Required Property Line Setbacks

	Minimum	Actual
Front	35	91'
Side	10	98'
Corner	70	NA
Rear	25	542'
Nearest Building	10	1802'

Section I
Sandy River Run
NTROR
RIVER

