

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940	0-2%	0-2%												
HORIZON 1 DEPTH		0-42"	0-43"												
Texture Group	.1941(A)(1)	S/LS	S/LS												
Consistence	.1941	VFR	VFR												
Structure	.1941(A)(2)	G/SG	G/SG												
Mineralogy	.1941(A)(3)	NS/NP	NS/NP												
<b>HORIZON 2 DEPTH</b>															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
<b>HORIZON 3 DEPTH</b>															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
<b>HORIZON 4 DEPTH</b>															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	S	S												
LONG TERM ACCEPTANCE RATE	.1955	1.0	1.0												

2 40' LINES  
32"-36" DEEP

