

SITE/SI EVALUATION FOR ON-SI WASTEWATER


APPLICANT NAME _____


DATE _____

RT

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		<i>12.36</i>												
Texture Group	.1941(A)(1)	<i>SEC 2 UNIT</i>												
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 2 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 3 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 4 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/.1956													
CLASSIFICATION	.1948													
LONG TERM ACCEPTANCE RATE	.1955													

M






SITE PLAN APPROVAL

DISTRICT *R-35* USE *Medium Density Residential*
 #BEDROOMS *3*
 Date *2-20-21*
 Zoning Administrator *[Signature]*

Required Property Line Setbacks

Front	Side	Corner	Rear	Nearest Building
Minimum 35'	Minimum 10'	Minimum 20'	Minimum 25'	Minimum 10'
Actual 115'	Actual 100'	Actual 120'	Actual 100'	Actual 10'

Must
on site
may not require
Pump



5x100
18"
MAX

550 1270

Changes for # 01-5-3047 Jannie Wimberly
 Changes were made to get house out of Septic Area
 by gutter as

