

SITE/S . EVALUATION FOR ON-S WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-20	0-14	0-20							
Texture Group	.1941(A)(1)	SL	SL	SL							
Consistence	.1941	VFR	VFR	VFR							
Structure	.1941(A)(2)	G	G	G							
Mineralogy	.1941(A)(3)	NS/NP	NS/NP	NS/NP							
HORIZON 2 DEPTH		20-38	14-32	20-34							
Texture Group	.1941(A)(1)	SCL	SCL	SCL							
Consistence	.1941	FR	FR	FR							
Structure	.1941(A)(2)	SBK/G	SBK/G	SBK/G							
Mineralogy	.1941(A)(3)	SS/SP	SS/SP	SS/SP							
HORIZON 3 DEPTH		38"	32"	34"							
Texture Group	.1941(A)(1)	C	C	C							
Consistence	.1941	FR	FR	FR							
Structure	.1941(A)(2)	SBK	SBK	SBK							
Mineralogy	.1941(A)(3)	SS/SP	SS/SP	SS/SP							
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948	PS	PS	PS							
LONG TERM		.4	.4	.4							
ACCEPTANCE RATE	.1955										

4 x 8' 75'
18" DEEP
ONCE

