

# SITE/SOI VALUATION FOR ON-SITE ASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-8	0-3	0-48'	0-6'						
Texture Group	.1941(A)(1)	SL	SL	C	SL						
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 2 DEPTH		8"-24"	3-6"		6"-12"						
Texture Group	.1941(A)(1)	SC	SC <sup>fill</sup>		SC						
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 3 DEPTH		24"	6"-12"		12"						
Texture Group	.1941(A)(1)	C	SL		SL						
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH			12"								
Texture Group	.1941(A)(1)		C								
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
OIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
APROLITE	.1943/.1956										
CLASSIFICATION	.1948	PS	PS	PS	PS						
LONG TERM ACCEPTANCE RATE	.1955	.4	.4	.4	.8						

