

# SITE/ L EVALUATION FOR ON-S : WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-8	0-16	0-24	0-18	0-18	—————→								
Texture Group	.1941(A)(1)	LS	LS	LS	LS	LS									
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 2 DEPTH		12-20	16-24	24-30	18-24	18-24	—————→								
Texture Group	.1941(A)(1)	SCL	SCL	SCL	SCL	SCL									
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 3 DEPTH		24-36	24-36	24-36	24-36	24-36	—————→								
Texture Group	.1941(A)(1)	SC	SC	SC	SC	SC									
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948														
LONG TERM ACCEPTANCE RATE	.1955	.3	.3	.3	.3	.3	—————→								

