# SITE/SC EVALUATION FOR ON-SI WASTEWATER

APPLICANT NAME _____ DATE _____

| FACTORS | | PROFILES | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| LANDSCAPE POSITION | .1940 | | | | | | | | | | |
| SLOPE (%) | .1940 | | | | | | | | | | |
| HORIZON 1 DEPTH | | 0-28 | 0-33 | 0-35 | | | | | | | |
| Texture Group | .1941(A)(1) | LS | LS | | | | | | | | |
| Consistence | .1941 | VFR | | | | | | | | | |
| Structure | .1941(A)(2) | CR | | | | | | | | | |
| Mineralogy | .1941(A)(3) | NS/NP | | | | | | | | | |
| HORIZON 2 DEPTH | | 28+ | 33+ | 35+ | | | | | | | |
| Texture Group | .1941(A)(1) | SCL | SCL | | | | | | | | |
| Consistence | .1941 | FR | | | | | | | | | |
| Structure | .1941(A)(2) | CR | | | | | | | | | |
| Mineralogy | .1941(A)(3) | SS/SP | | | | | | | | | |
| HORIZON 3 DEPTH | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| HORIZON 4 DEPTH | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| SOIL WETNESS | .1942 | | | | | | | | | | |
| RESTRICTIVE HORIZON | .1944 | | | | | | | | | | |
| SAPROLITE | .1943/.1956 | | | | | | | | | | |
| CLASSIFICATION | .1948 | PS | PS | | | | | | | | |
| LONG TERM ACCEPTANCE RATE | .1955 | .5 | .5 | | | | | | | | |