


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-12	30-40	30-40	36-60	0-36	0-12								
TEXTURE GROUP	.1941(A)(1)	LS	⊙	⊙	⊙	Clay	LS								
CONSISTENCE	.1941		Fill	Fill	F-1										
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 2 DEPTH		12-18	0-12	0-12	0-4		12-18								
TEXTURE GROUP	.1941(A)(1)	scl	LS	LS	LS		scl								
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 3 DEPTH		18-30					18-30								
TEXTURE GROUP	.1941(A)(1)	sc					sc								
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942	26"					28"								
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948														
LONG TERM ACCEPTANCE RANGE	.1955														

Refer to
O.T. will
Need P.T.s
for AREA 4
Fill



At
Surface

Hole
APPEARS
To Be mixed
Soils from either
cutting or Filling

- A
CR2 @ 20"
- B
CR2 @ 24"
- C
FILL 5"
CR2 @ 36"
- D
FILL 21"
CR2 @ 40"
- E
FILL 48"


Required Property Line Setbacks

	Required	Actual
Front	35	35
Side	10	28
Corner	20	40
Rear	25	137
Nearest Bldg.	10	<

lot 22

THE PLAN APPROVAL
 DISTRICT RA-20M USE DWMT
 #BEDROOMS 3
15 March 2007 C Bell
 Date Zoning Administrator

McFryden DR



lot 20

Karnes St
111