

SITE/SOIL EVALUATION FOR ON-SITE WASTE WATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-12	0-12	0-12	0-18						
TEXTURE GROUP	.1941(A)(1)	SL	SL	SL	SL						
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 2 DEPTH		12-30"		18-39	18-36						
TEXTURE GROUP	.1941(A)(1)	SC2		SC2	SC2						
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 3 DEPTH				34"							
TEXTURE GROUP	.1941(A)(1)			~50%pm							
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942	23"	0"	32"							
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948	PS	US	PS	P						
LONG TERM ACCEPTANCE RANGE	.1955	.4		.4	.4						

4 x 75'
 1-2 18"
 3-4 12" 6" COVER

