

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-30	0-30	0-8	0-6						
TEXTURE GROUP	.1941(A)(1)	L	L	SL	SL						
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 2 DEPTH		30"	30"	18"	6-24						
TEXTURE GROUP	.1941(A)(1)	SL	SL	SL	CL						
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 3 DEPTH					24"						
TEXTURE GROUP	.1941(A)(1)				C						
CONSISTENCE	.1941				FR						
STRUCTURE	.1941(A)(2)				VS / VP						
MINERALOGY	.1941(A)(3)				SEXP						
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948	P3	P3	XS	P3						
LONG TERM ACCEPTANCE RANGE	.1955	.7	.7	.5	-.3						

