

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

| FACTORS                    |             | PROFILES |   |   |   |   |   |   |   |   |    |  |  |  |
|----------------------------|-------------|----------|---|---|---|---|---|---|---|---|----|--|--|--|
|                            |             | 1        | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |  |  |  |
| LANDSCAPE POSITION         | .1940       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| SLOPE (%)                  | .1940       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| HORIZON 1 DEPTH            |             | 12-48    |   |   |   |   |   |   |   |   |    |  |  |  |
| TEXTURE GROUP              | .1941(A)(1) | SC1      |   |   |   |   |   |   |   |   |    |  |  |  |
| CONSISTENCE                | .1941       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| STRUCTURE                  | .1941(A)(2) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| MINERALOGY                 | .1941(A)(3) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| HORIZON 2 DEPTH            |             |          |   |   |   |   |   |   |   |   |    |  |  |  |
| TEXTURE GROUP              | .1941(A)(1) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| CONSISTENCE                | .1941       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| STRUCTURE                  | .1941(A)(2) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| MINERALOGY                 | .1941(A)(3) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| HORIZON 3 DEPTH            |             |          |   |   |   |   |   |   |   |   |    |  |  |  |
| TEXTURE GROUP              | .1941(A)(1) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| CONSISTENCE                | .1941       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| STRUCTURE                  | .1941(A)(2) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| MINERALOGY                 | .1941(A)(3) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| HORIZON 4 DEPTH            |             |          |   |   |   |   |   |   |   |   |    |  |  |  |
| TEXTURE GROUP              | .1941(A)(1) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| CONSISTENCE                | .1941       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| STRUCTURE                  | .1941(A)(2) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| MINERALOGY                 | .1941(A)(3) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| SOIL WETNESS               | .1942       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| RESTRICTIVE HORIZON        | .1944       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| SAPROLITE                  | .1943/.1956 |          |   |   |   |   |   |   |   |   |    |  |  |  |
| CLASSIFICATION             | .1948       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| LONG TERM ACCEPTANCE RANGE | .1955       | 5        |   |   |   |   |   |   |   |   |    |  |  |  |

17240  
18

1=100

TE

PLANNING DIRECTOR

**Required Property Line Setbacks**

Front

| Minimum | Actual |
|---------|--------|
| 35      | 140    |
| 10      | 534    |
| 25      | 145    |
| 10      |        |

PLAN APPROVAL

DISTRICT RA20R USE DW  
 ROOMS 3

REVIEW OFFICER OF THAT THE MAP OR PLAT TO WHICH THIS CERTIFICATION REQUIREMENTS FOR RECORDING.

DATE 4-11-02  
 Zoning Administrator


REVIEW OFFICER

*Refer to deed work*

A PRIVATE  
 T LOT(S) ON  
 T FINAL  
 APPROPRIATE  
 ECIFIC USE  
 E AT THE  
 EPRESENT

ENTATIVE

X 70' SIGHT TRIANGLES



MAP BK. 2001 PG. 425  
 PARCEL # 09-9568-0004

MAP BK. 2001 PG. 425  
 PARCEL # 09-9568-0004-01