

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-16	0-18	0-18	0-18	0-17	0-18	0-18							
TEXTURE GROUP	.1941(A)(1)	LS	LS	LS	LS	LS	LS	LS							
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 2 DEPTH		16-24	18-21	18-24	18-24	12-18	18-28	18-24							
TEXTURE GROUP	.1941(A)(1)	SC	SC	SC	SC	SC	SC	SC							
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 3 DEPTH		24-30	24+	24+	24+	18-28	28+	28+							
TEXTURE GROUP	.1941(A)(1)	exp	exp	exp	exp	SC	SC	SC							
CONSISTENCE	.1941	SC	SC	SC	SC		exp	exp							
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)						exp	SC							
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942	22	24	23											
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948														
LONG TERM ACCEPTANCE RANGE	.1955						2	3							

Ryan  
 Per...  
 Per... L.P.M.

57576.0  
 400 At soil  
 5200 12"