

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-6	0-9												
TEXTURE GROUP	.1941(A)(1)	CL	CL												
CONSISTENCE	.1941	BE	BE												
STRUCTURE	.1941(A)(2)	SH	SH												
MINERALOGY	.1941(A)(3)	S&P	S&P												
HORIZON 2 DEPTH		0-34	0-82												
TEXTURE GROUP	.1941(A)(1)	C	C												
CONSISTENCE	.1941	E	E												
STRUCTURE	.1941(A)(2)	ABK	ABK												
MINERALOGY	.1941(A)(3)	S&P	S&P												
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948	B	B												
LONG TERM ACCEPTANCE RANGE	.1955	.25	.25												

②

①

