

OPERATIONS PERMIT

02-5-5003

Name: (owner) Danida Gitantis

New Installation Septic Tank

Property Location: SR# NC24 (Hill Brook)

Repairs

Nitrification Line

Subdivision Bridlewood Hills

Lot # 14

TAX ID# _____

Quadrant # _____

Contractor: J. Faircloth

Registration # _____

Basement with Plumbing: Garage:

Water Supply: Well Public Community

Distance From Well: 50 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other _____

Size of tank: Septic Tank: 1000 gallons Pump Tank: _____ gallons

Subsurface Drainage Field No. of ditches 1 exact length of each ditch 300 ft. width of ditches 3 ft. depth of ditches 18 in.

French Drain: _____ Linear feet

Date: 8-1-02

PERMIT NO. _____

Inspected by: J. Walters
Environmental Health Specialist

