

SITE/SOIL EVALUATION FOR ON-SITE W TEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-24	0-28								
TEXTURE GROUP	.1941(A)(1)	SL	SL								
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 2 DEPTH		24-28	28"								
TEXTURE GROUP	.1941(A)(1)	SL	SL								
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 3 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948	P5	P5								
LONG TERM ACCEPTANCE RANGE	.1955	.5	.5								

I 3x80'

R 3x80'



Required Property Line Setbacks

	Minimum	Actual
Front	35	128
Side	10	33
Corner	20	
Rear	25	590
Nearest Building	10	

SITE PLAN APPROVAL

DISTRICT 11A USE Residential
 #BEDROOMS 3
22 Jul 02 Chell
 Date Zoning Administrator

Caroline Locklear