

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-12	0-10	0-10"											
TEXTURE GROUP	.1941(A)(1)	SL	SL	SL											
CONSISTENCE	.1941	VFR	YFR	VFR											
STRUCTURE	.1941(A)(2)	G	G	G											
MINERALOGY	.1941(A)(3)	NS/NF	US/NP	NS/NP											
HORIZON 2 DEPTH			10-38"	10"r											
TEXTURE GROUP	.1941(A)(1)		SC2	SC2											
CONSISTENCE	.1941		FR	FR											
STRUCTURE	.1941(A)(2)		SBK	SBK											
MINERALOGY	.1941(A)(3)		NS/NP	NS/NP											
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942	10"	30"	30"											
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	US	P5	P5											
LONG TERM ACCEPTANCE RANGE	.1955	B	.4	.4											

4x25' @ 18"

