

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-18													
TEXTURE GROUP	.1941(A)(1)	LS													
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 2 DEPTH		18-76													
TEXTURE GROUP	.1941(A)(1)	SL													
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 3 DEPTH		76-42													
TEXTURE GROUP	.1941(A)(1)	SL													
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948														
LONG TERM ACCEPTANCE RANGE	.1955	.4									.7				


$\frac{2}{3} \sqrt{40}$   
 $\frac{4}{3} \sqrt{36}$   
 $\frac{3}{3}$




Gr  
M14  
#97

WA  
MH  
WA

Box



Box



GC  
MH  
HW



dog on curb

tw  
MH  
MH

May  
get  
A

How  
in vol.  
could  
non be