

SITE/SOIL EVALUATION OR ON-SITE WASTE EVALUATION

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-30"	0-20"								
TEXTURE GROUP	.1941(A)(1)	LS	LS								
CONSISTENCE	.1941	VFR	VFR								
STRUCTURE	.1941(A)(2)	G/CR	G								
MINERALOGY	.1941(A)(3)	NS/NP	NS/NP								
HORIZON 2 DEPTH		30"-40"	20-32"								
TEXTURE GROUP	.1941(A)(1)	SCL	C								
CONSISTENCE	.1941	FR	FR								
STRUCTURE	.1941(A)(2)	SBK	SBK								
MINERALOGY	.1941(A)(3)	SS/SP	SS/SP								
HORIZON 3 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948	PS	PS								
LONG TERM ACCEPTANCE RANGE	.1955	.5	.4								

INITIAL
4x80' @ 18"

REF
25% RED. 5 Y.
3x75'

