

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		B-48	O-48												
TEXTURE GROUP	.1941(A)(1)	S	S												
CONSISTENCE	.1941	VFR	VFR												
STRUCTURE	.1941(A)(2)	G/C2	G/C2												
MINERALOGY	.1941(A)(3)	N3/MP	N3/MP												
HORIZON 2 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943, 1956														
CLASSIFICATION	.1948	B	B												
LONG TERM ACCEPTANCE RANGE	.1955	8	8												

2x75' @ 24"
CONV.
REPAIR

