

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-	0-6	0-6	0-40	0-40	0-6	0-40"			
TEXTURE GROUP	.1941(A)(1)	0-	CLAY S	S	S	S	S	S			
CONSISTENCE	.1941		HR								
STRUCTURE	.1941(A)(2)		G								
MINERALOGY	.1941(A)(3)		USHR								
HORIZON 2 DEPTH			6"~30"	6"~	40"	40"	6"	40"			
TEXTURE GROUP	.1941(A)(1)		SC	PM	SC	SC	SC	SC			
CONSISTENCE	.1941		FR								
STRUCTURE	.1941(A)(2)		SR								
MINERALOGY	.1941(A)(3)		S/R								
HORIZON 3 DEPTH			30"~								
TEXTURE GROUP	.1941(A)(1)		PM								
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942	0"									
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948	U>	PS	US							
LONG TERM ACCEPTANCE RANGE	.1955		.4		.2	.8	.4	.8			

~~4 x 50" @ 24" MAX~~
MEET ON SITE

