


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-8	0-6	0-6											
TEXTURE GROUP	.1941(A)(1)	SL	SL	SL											
CONSISTENCE	.1941	Vfr	Vfr	Vfr											
STRUCTURE	.1941(A)(2)	C	C	C											
MINERALOGY	.1941(A)(3)	Wxy	Wxy	Wxy											
HORIZON 2 DEPTH		6-24	6-30	6-24											
TEXTURE GROUP	.1941(A)(1)	SC	SC	SC											
CONSISTENCE	.1941	F	F	F											
STRUCTURE	.1941(A)(2)	SLK	SLK	SLK											
MINERALOGY	.1941(A)(3)	SLK	SLK	SLK											
HORIZON 3 DEPTH		24+													
TEXTURE GROUP	.1941(A)(1)	phys. only too wet													
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942		28"	24"											
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948		U10	U15											
LONG TERM ACCEPTANCE RANGE	.1955		13	13											

see 4

1 Existing



3