

SITE/SOIL EVALUATION FOR ON-SITE WATER

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-10	0-14											
TEXTURE GROUP	.1941(A)(1)	SL	SL											
CONSISTENCE	.1941	VFR	VFR											
STRUCTURE	.1941(A)(2)	G	G											
MINERALOGY	.1941(A)(3)	NS/NP	NS/NP											
HORIZON 2 DEPTH		10-30	10-36											
TEXTURE GROUP	.1941(A)(1)	SC/L	SC/L											
CONSISTENCE	.1941	FR	FR											
STRUCTURE	.1941(A)(2)	G/SBK	G/SBK											
MINERALOGY	.1941(A)(3)													
HORIZON 3 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 4 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/1956													
CLASSIFICATION	.1948	PS	PS											
LONG TERM ACCEPTANCE RANGE	.1955	.5	.5											

A x 60 @ 12"
EQUAL RIPAIR

